

## Project Info



03 / 08 / 2011



CC13



10sqm



1 longitudinal layer



Lowestoft, Suffolk, UK



Local authority



CC installed onto steel pile beach groyne to block voids, prevent accident and reduce beach loss.



Completed repaired groyne section at high tide



Steel pile beach groyne, Lowestoft



Groyne section in disrepair with dangerous voids



Excavating groyne section



Cutting CC13 on site



Bolting CC section to groyne



Hydrating the CC section with sea water

